



	This is where the boom goes	
<u> </u>	T —	- -
	· 	
Boom Spar (6mm) make 2		
	 	
	1	
	· 	
Room half (3mm) make 4		
Boom half (3mm) make 4		B
		Make this slot
	<u> </u>	
_ 	· = 	/-
		X


⊨ = = =	= = = <i></i>	
		'
	Boom Spar (6mm) make 2	
		1
		$\frac{1}{1}$ — — — — — —
		!
		<u> </u> -
	Boom half (3mm) make 4	
		[
		<u> </u>
		1
⊨ = = =	= = = =	














 	[[
	•
	Carbon tube slot. Make tight fit

l				
			I	
			· —+	
			1	
l				
			二	
			1	
			ı	
<u>'</u>			l	
			I	
 			i I	
	This	is where the boom goes	ı	
<u> </u>	 			
l			ı	

